



TRON (1982) HELMET
NECK VISOR

Cooper SK-2000 S
Left Side
Face Out

2 existing
holes in
helmet

Must drill this
hole in helmet